


Shift Position Indicator Circuit Diagram



PCM Connector Terminal Locations



A □ (51P)




B ▲ (51P)

Terminal side of female terminals



C ○ (51P)



PCM Connector Terminal Locations



A □ (51P)



B ▲ (51P)

Terminal side of female terminals



C ○ (51P)